LOW COST MANUFACTURING INC

EXAMEDLE OF WORK ORDER

Scheduled Maintenance Work Order 7/02/2019 PERIOD ENDING. WORK ORDER NO... 15.024 PRIORITY..... 0 WO REQUEST #..... SUPERVISOR..... ASSIGNED TO CR CARL RAMSAY ENTERED 7/02/2019 2:47 PM TECH BLDG EQUIPMENT.....11 REQUESTED BY.CARISSA LEWIS **STARTED** 11 LOCATION.....TECH BLDG DEPT SERIAL.... MODEL..... SHIFT LINE..... MANUFACTURER... WORK ORDER HEADER: CHECK A/C FOR TE-103 AND OTHER PROBLEMS STATUS: DATE DO TIME INITIALS SEQ# DESCRIPTION APPLY ALL SAFETY PROCEDURES BEFORE STARTING YOUR WORK.... THINK SAFETY!!! CHECK A/C FOR TE-103 AND OTHER PROBLEMS. TE 103 (SANDI DANIELS CLASSROOM). SHE'S HAVING PROBLEMS WITH GETTING IT COOL IN THE CLASSROOM AND SHE AND HER STUDENTS ALSO NOTICED THAT THE PAPER IS DAMP FORM HUMIDITY AND THAT HER CHAIRS HAS MOLD ON THEM. IF WE CAN GET SOMEONE TO CHECK ON THESE TWO ISSUES IT'LL BE GREATLY APPRECIATED. SANDI WILL BE IN HER OFFICE FOR ANY QUESTIONS. (TE 9) Total Time: ADDITIONAL LABOR Date Initials Initials Time Date ADDITIONAL PARTS QTY Used Description Location Part Number WHEN WORKING ON A MACHINE MAKE SURE THAT YOU USE YOUR LOCKOUT AND TAG OUT SYSTEM!!!!! WHEN YOUR WORK IS COMPLETED TEST RUN YOUR EQUIPMENT. TEST ALL SAFETIES AND MAKE SURE ALL GUARDS ARE IN PLACE. LOOK FOR POTENTIAL HAZARDS AND CORRECT IF NEEDED. CLEAN YOUR WORK AREA AND RETURN ANY UNUSED PARTS TO THEIR PROPER LOCATIONS. NOTIFY YOUR SUPERVISOR AND MAKE OUT A WORK ORDER FOR ANY WORK THAT YOU CANNOT COMPLETE. Comments ___ _ ____ -Approved By: _____ Inspected By: _____

EXAMPLE OF FIRE EXT. PREVENTIVE MAINT.

M	MONTHY FIRE EXTINGUISHER/EXIT/EMERGENCY LIGHT REPORT								
	EXIT LTS.	EMER.	FIRE EX.	GOOD	BAD	INITIAL	DATE	COMMENTS	
Administration Building 1st Floor									
WEST ENTRY/BUSINESS OFFICE	1								
CENTRAL by ROOM 124		1	1						
WEST HALL by ROOM 114		<u> </u>	1				1		
WEST STAIRWELLS	1	2							
FRONT ENTRY	1								
EAST ENTRY	2	1	1					·	
CENTRAL HALL by ROOM 140		1	1						
EAST HALL BY HANDICAP RR			1						
EAST HALL by ROOM 143			1						
Administration Building 2nd Floor			•	1					
EAST STAIRWELL	1	1							
BY WOMEN HANDICAP RR			1						
CENTRAL HALL by ROOM 248-242		1	1						
CENTRAL STAIRWELL	1	1							
CENTRAL HALL/WEST END		1	1						
WEST HALL by ROOM 200			1						
Administration Building Basement]								
STAIRWELL LANDING	1		_						
ENROLLMENT SERVICES	1	1	1				<u>.</u>		
ELEVATOR CLOSET	<u> </u>		1						
SHOOTING RANGE	<u></u>		1		<u> </u>				
Technical Building 1st Floor	<u> </u>						<u> </u>	,	
FRONT ENTRY	1	1	1						
SOUTH/WEST ENTRY	2	1	1						
EAST ENTRY	2	1	1						
WEST HALL by ROOM 111	2		1	_					
NORTH/WEST ENTRY	1	<u> </u>	1		<u> </u>	L	ļ		
NORTH ENTRY	1		1		ļ		1		
IORTH/SOUTH & CENTRAL STAIRWELLS		9_		<u> </u>			<u> </u>		
NORTH HALL	2	ļ <u>.</u>	1	ļ		ļ. <u>.</u>			
Technical Building 2nd Floor									
NORTH HALL	1		1						
NORTH WEST HALL/by TE-21-20	3	_	2	<u> </u>	<u> </u>		<u> </u>		
WEST HALLWAY	2		1			ļ			
ROOM 214-213 INSIDE	<u> </u>		2	ļ	↓	 	ļ		
ELEVATOR MAINT. ROOM by 210		ļ	1		<u> </u>	<u> </u>	ļ		
ACROSS FROM TE-211	1	_	1	1	ـــــ	<u> </u>	ļ		
SOUTH HALL	4		3	ļ	<u> </u>		1.		
Business Building 1st Floor		<u> </u>		<u> </u>			<u> </u>		
NORTH/EAST ENTRY	1	ļ	1	 	\bot	ļ	ļ		
CENTRAL HALL	2	1		_	 	<u> </u>	↓		
BB 140 OLD CAFÉ	_	1	1	<u> </u>	 	ļ	 	<u> </u>	
BB 145	1	1	 	-	+	1. —	+		
KITCHEN by STOVE	 	1	1 1	-	+	 -	+		
OLD CAFÉ STORAGE ROOM	1 -	+	1_1_	 	┦	+ -	+		
WEST ENTRY	1	+	+ -	 	+	 	+		
SOUTH HALL/ENTRY/RM100	4	+	1	-	+	1			
ELEVATOR MAINT, ROOM	 	+ -	1 1		-	┼	+		
ROOM 106 BB-136/ NURSE STORAGE	 	1	2	-	+-	 	 -		

	ONTHY FIR							
	EXIT LTS.	EMER.	FIRE EX.	GOOD	BAD	INITIAL	DATE	COMMENTS
Business Building 2nd Floor			·					**
SOUTH HALLWAY	4							
WEST CENTRAL HALL	2		2					
CENTRAL HALL	2		1					
EAST/CENTRAL HALL	2		1					
NORTH HALLWAY	2							
PAINT STORAGE								
INSIDE	1		1					
Learning Resource Center								
FRONT ENTRY	2		1	-	<u> </u>			
STUDY AREA	2	<u> </u>	2					
SOUTH EMERGENCY EXIT	1		2	1				
WALL BY STAFF DOOR TO STUDY AREA	2							
OFFICE AREA HALLWAY	1		1					
ALARM/STORAGE ROOM			1					
BREAKROOM EXIT	1		<u> </u>					
WORK STATION EXIT	1			Ì				
EXTERIOR MECHANICAL ROOM			1					
Career Academy And Pathways								
FRONT LOBBY	1	1	1			-		
KITCHEN		1	1					
WATER FOUNTAIN/COMP.LAB			2		1			
Physical Plant						-		
BREAKROOM/TRAINING	2	1	1		 		 	
SOUTH/WEST SHOP AREA	1	 		 -	 	ļ	 	
NORTH/WEST SHOP AREA		 	2	 	 	 		
SOUTH/EAST SHOP AREA	-	+	1		<u> </u>			
NORTH/EAST SHOP AREA	1	1	1	 	┼-	<u> </u>	 	
INVENTORY/STORAGE AREA	· · · · · · · · · · · · · · · · · · ·	†	1	 			t	
VEHICLE CARPORT POST		1	1		 		<u> </u>	
FUEL SHED			1				1	
PUSH MOWER STORAGE		†	1			1		
FORK LIFT	1		1					
Maintenance Building						3 ,		
FRONT ENTRY	2	· -	1					
WELDING AREA	1	† – –	1					
SOUTH END CENTRAL HALL	1		1		<u> </u>			
CLASSROOM	1		1					
WELDING BOOTH AREA		1	3					
DOCK ENTRANCE			1					
CARPENTER SHOP			1					<u> </u>
Environmental Training Academy								
LOBBY			1					
HALLWAY/COPYROOM	1		1					
FRONT ENTRANCE	1			<u> </u>		ļ	1	
CLASSROOM/CONFERENCE RM	1	ļ	2		1	↓	<u> </u>	
Enviromental Lab Building							<u> </u>	
EAST ENTRY	1	1	1			ļ	1	
EAST WALL /BAY EXIT	2	1				ļ		
NORTH BAY DOORS/WALL	1	1			<u> </u>			
UPSTAIRS EQUIPMENT ROOM			1]	

J.	AONTHY FIR	E EXTIN	IGUISHER	I/EXIT/E	MERC	SENCY L	IGHT RE	PORT	
	EXIT LTS.	EMER.	FIRE EX.	GOOD	BAD	INITIAL	DATE	COMMENTS	
Gymnasium			- 4		100	\$	11 5		
FRONT ENTRY	1		1						
WORKOUT ROOM/EAST EXIT	2		1						
LOBBY AREA/EXIT	1		2						
WEST EXIT	1		1						
NORTH WALL BALL COURT	1	1	1						
SOUTH WALL BALL COURT	2	1							
P.E. Office	1		1						
SOUTH STORAGE	1		1						
Student Center						[
NORTH ENTRY/LOBBY	1		1						
CENTRAL HALL	7								
BOOKSTORE/ STORAGE	1		1			·			
STUDENT DINING/KITCHEN	2		1						
SOUTH ENTRY/LOBBY	1		1						
MECHANICAL/MAINTENANCE HALL	3		2						
MECHANICAL ROOM	1		1						
GRAND HALL 1	3		1						
GRAND HALL 2	3		1						
AUTO SHOP									
NORTH ENTRY/BAY DOORS	1		2						
NORTH DOOR CLASSROOM	1								
BATH ROOM HALL	2	1							
EAST BAY/SHOP WALL		1	2						
WEST AUTO RACK WALL			2						
UPSTAIRS STORAGE			1						
FIRE TRAINING ACADEMY									
LOBBY	1								
CENTRAL HALL	2	1	1						
EAST HALLWAY	1	1	1						
UPTOWN CENTER STREET LEVEL					1				
MAIN ENTRY	1						Ţ" ·		
RECEPTION AREA	1		1		 				
GENERAL OFFICE HALLWAY	3	<u> </u>	<u> </u>	1			1		
OFFICE CUBICLE HALL	1						1		
UPTOWN CENTER LOWER LEVEL									
ELEVATOR LOBBY	1	 	· ··-	1	-	 	 		
ELEVATOR MECHANICAL ROOM	 	<u> </u>	1	<u> </u>	 	<u> </u>	1		
EAST SIDE HALLWAY	2		1	 		 	1		
WEST SIDE HALLWAY	4	1	2	1			1		
MECHANICAL ROOM	1		<u> </u>				1		
ROSS CENTER GARAGE			 	1	1	<u> </u>	1		
BAY WALL	_	 	1	 	1	 	†		
ROSS CENTER		+	1 -	 -	+ -	 	 		
FRONT ENTRANCE	1	 	 	+	 	+	+		
	1	 	1		+-	+	 		
EAST SIDE HALLWAY	1 2		+ -	+	+	+	 		
WEST EXIT		1	1	+	+-	 	+		
SOUTH ENTRANCE	1	 	+ -	 	+-	+	+		
MULTI-PURPOSE AREA	4		1	+	+-	 	+		
WIULTI-PURPUSE AREA	4	<u> </u>	<u> </u>	Щ.	1	<u> </u>	—	1	

	EXIT LTS.	EMER.	FIRE EX.	GOOD	BAD	INITIAL	DATE	COMMENTS
D DORMITORIES								
FRONT ENTRANCE	1							
CENTRAL HALL NORTH	1	1	1	· · · · ·				
CENTRAL HALLWAY SOUTH	1	2	1					
D DORMITORIES 2nd FLOOR								
CENTRAL HALL NORTH	2	1	1					
CENTRAL HALL SOUTH	1	1	1					
KITCHEN	1		1					
MECHANICAL MAINTENANCE BUILDING								
FRONT ENTRY	1	1	1					
HALLWAY	2		1					
EAST/WEST HALL	1	1	1					
MECHANICAL WELDING							7.	of the second second second
NORTH ENTRY/BAY DOORS	2	1	1	· - · - ·				
SHOP AREA NORTH WALL	1	2	 					
SHOP AREA SOUTH WALL	1							
AVATION HANGER								
MAIN ENTRANCE/WEST WALL	2	1	3					
CLASSROOMS (2)		2						
EAST EXIT/WALL	1	1	3					
northwest entrance	1	·						
UPSTAIRS WALKWAY			1					
STUDENT APARTMENTS							11	
EAST APARTMENTS			2					
WEST APARTMENTS 1 & 2			4					
DAYROOM NORTHWALL			1		<u> </u>			
MAINTENANCE HALLWAY			2					
SECURITY								
PATROL UNIT IN TRUNK			1					
AFTA FIREHOUSE		-						
NORTH ENTRY	1	1						
NORTH HALLWAY	2		2					
BREAKROOM ENTRY/EXIT	1	1						
TRUCK BAY NORTH WALL		3						
TRUCK BAY SOUTH WALL		3						
WEST HALLWAY NORTH ENTRY	1	1						
DAYROOM WEST EXIT	1							
WEST HALLWAY			2					
WEST HALL SOUTH EXIT	1	1						
ELECT. MAINTENANCE (OUTSIDE)			1					

Signature:
Date: